

General Notes :

All dimensions are in inches.

Package / body size can affect dimensions and tolerance for each tool.

Tools will accept flat unformed parts with tie bars removed.

Free training at Fancort is strongly suggested.

Upper and lower radius should be matched and suggested 1.5 x lead material thickness minimum to reduce sticking.

Leads should be tinned after forming, this keeps the tools clean and accurate and prevents sticking to the anvils.

For quoting, please send us your forming specifications for all of the devices that you want to process.

Fancort will review and suggest options based on your scope of work and devices to be formed.